Navajo Abandoned Uranium Mine Site Screen Report

This form is for use at the site of abandoned uranium mines (AUM) located on Navajo Nation lands. Applicable sites include all mine and mine features that have or have not undergone reclamation by the Navajo Abandoned Mine Lands Reclamation Program, including features, adits and pits. Applicable sites also include all AUM sites listed in the USEPA CERCLIS database, all sites listed in the 2008 AUM GIS Report issued by USACOE and USEPA, all AUM sites on allotment lands associated with the Navajo Nation, and any and all AUM sites lands not listed in any database located on Navajo lands. Reconnaissance of any sites located on lands adjacent to Navajo lands but that are or may be impacting Navajo lands will need to be coordinated with the authorities appropriate to those lands.

The purpose of the form is to ascertain the status and location of the identified AUM site, to record all immediate site information associated with the mine site and to document the recommendation and/or decision on what additional steps, if any, are needed at the site.

Section 25

Navajo AUM Eastern Region

Prepared by:

Weston Solutions, Inc.

Contract: W91238-06-F-0083

12767.063.496.1111

May 2009

Part I Site Identification, Location and Status

Site Names and ID numbers as applicable

Mine ID: 363, 365, 366

Map ID: E93 (363)

E98 (365) E99 (366)

CERCLIS: NOT ASSIGNED

New Mexico Mining and Mineral Division ID: 363 – NM0070

365 - NM0044366 - NM0044

New Mexico Bureau of Geology and Mineral Resources: 363 - NMMK0219

365 - NMMK0218 366 - NMMK0218

Local name / Aliases:

363 – Section 25 SEQ, Desideiro, Amiran, Operation Haystack, Sec. 25 Strip Complex,

Sec. 25 Open Pit

365 – NW ¼ Section 25, Vanadium No. 1, Rock No. 1, Section 25 Shaft, Open Pit

366 – Section 25 SEQ, Desideiro, Amiran, Operation Haystack, Sec. 25 Strip Complex,

Sec. 25 Open Pit

New Mexico MMD District: Ambrosia Lake

Lat/Long: 35.3330061285 N / -107.851948576 W (#363)

35.3271869882 N / -107.848825328 W (#365) 35.3230455624 N / -107.843177580 W (#366)

Nearby road and highway: Haystack Road / NM-334 Local Post Office: Prewitt, NM

Land Status: check one or more and provide ownership and contact information below

Tribal Trust Land	
Tribal Fee Land	
Allotment	
Fee land	
Public lands	
Private	\boxtimes
Bureau of Land Mgmt	\boxtimes
State	\boxtimes

Ownership and contact information: The mine site property is classified as State, Bureau of Land Management, and private land. New Mexico MMD identifies the surface owners as Elkins Real Estate & Berryhiill Ranch Ltd, and owner of the mineral rights as The Newmont Mining Corporation. Due to locked gates and private property, Weston was unable to access the site.

Part II Site Observations

Observed Structures: list number of and describe human habitation status of structures at the following distances from mine:

0 to 200 feet: None 200 feet to 0.25 mile: None

Observed Public or commercial structure: list and describe all schools, clinics, Chapter Houses, places of business and any other structure used by members of the community at the following distances:

0 to 200 feet: None 200 feet to 0.25 mile: None

Levels measured around the perimeter(s) of the identified structure(s):

None

Observed water sources: list the number and type of wells and surface water sources that are potentially used for human consumption at the following distances from the mine:

0 to 0.25 miles: None 0.25 miles to 4 miles: None

Sensitive environments: note and describe all sensitive environments located within visible range of the mine site, including: wetlands, endangered species habitats and approximate locations of sites that may be under protection of the government of the Navajo Nation.

None observed

Known Site History: include information from interviews with Chapter officials and residents.

Note information on mine ownership, period of operation, and type of mining operation.

Section 25 mine consists of 3 separate mine sites, with a total surface area of 664,174.41 square meters, with an additional 43,791.16 square meters of underground workings. Any historical information pertaining to mining operations and historical ownership of the mine site appeared to be unclear. The New Mexico Mining and Minerals Division identified the operator of Site ID# 365 from 1963-1967 as Farris Mines; Site ID# 363 from 1952-1964 as Haystack Mountain Development Company; and in 1981 as Amiran Co. Ltd./Reserve Oil & Minerals; and Site ID# 366 in 1951 as ATSF RR; 1955-1961 as Haystack Mountain Development Corp.; 1962-1965 as Santa Fe Pacific; 1970-1972 as United Nuclear/Bailey & Fife; and 1980-1981 as Amiran/Reserve Oil & Minerals.

Part III Type, number and reclamation status of mine features

Provide description and reclamation status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all reclamation caps.

Reclamation status of the mine site is currently unknown. Due to locked gates and private property, Weston was unable to access the mine site. According to the New Mexico Mining and Mineral division, at Site ID# 365 during the 1980s Amiran/Reserve backfilled features after lease expired; in 1993 Santa Fe Pacific reclaimed & reseeded; in 1994 additional reclamation occurred, debris was removed, and a rainwater impoundment was built for livestock.

Part IV Summary of radiological readings

Note: Due to locked gates and private property, Weston was unable to access the mine site.

Background Locations - None

Mine site: Section 25
- See Figure 1

Nearby Structure Perimeter - None

Describe any other radiological measurements:

Radiological measurements collected for the New Mexico Mining and Minerals Division during a 2008 field screening survey found gamma radiation levels at Site ID# 365 with a background at 20-30 counts per second (cps); waste at 900 cps; and pits at 2,000-3,300 cps; Site ID# 363 with a background at 20-30 cps; and dumps at 3200 cps; and Site ID# 366 with a background at 20-30 cps; waste at 900 cps; and pits at 2,000-3,300 cps. Measurements collected for the New Mexico Environment Department found gamma radiation levels at Site ID# 363 of an adit at 40 cps; a limestone cut trash dump at 142 cps; above the arroyo at 177 cps; a vent hole at 48 cps; a drainage from the limestone cut at 40 cps; waste rock at 558 cps; and a stock tank at the end of the drainage at 177 cps.

Part V Site sketch of all mine features and readings, including locations of all structures, sources of potential drinking water and any other important features and radiological readings.

Presented in Figure 1

Part VI Response Action Summary

Site Name(s): Section 25 New Mexico MMD District: Ambrosia Lake

Decision Criteria

Is there an unreclaimed waste pile at the site? None observed

At what distance from the waste pile is the nearest residential structure located? N/A

At what distances from the waste pile are there potential drinking water sources? N/A

Is there a reclamation cap or sealed adit in place at the site? None observed

Is the cap/seal functionally intact? N/A

Is the cap/seal sufficiently degraded to create a concern about releases? N/A

At what distance from the cap/seal is the nearest domestic structure located? N/A

At what distance from the cap/seal is the nearest potential drinking water source? N/A

Summary of emergency response factors

None

Summary hazard ranking system factors

None

Summary of reclamation factors

Reclamation status of the mine site is currently unknown

Part VII Photos



Photo 1. Locked gate on road leading towards Section 25 mine site



Photo 2. Locked gate leading towards Section 25 mine site



Photo 3. Fenced area leading towards Section 25 mine site

The following photographs were collected by the New Mexico Environment Department:



Open pit area (Section 25 #363) adit



Open pit area (Section 25 #363) bulldozer cut into limestone, current trash dump area



Open pit area (Section 25 #363) facing east towards possible reclaimed area



Open pit area (Section 25 #363) facing southeast, overlooking mined area



Open pit area (Section 25 #363) waste rock near drainage



Aggreagate pit area (Section 25 #366) facing the southwest



SEQ area (northwest corner of Section 25 #366) facing the west

Part VIII Contacts Reports and Information

Name_Susan A. Lucas Kamat
Title or official role (if any) AUM Data Manager – New Mexico Mining & Mineral Division
Telephone number(505) 476-3408 fx: (505) 476-3408
Information provided <u>Background information and findings from 2008 New Mexico MMD</u>
Survey of mining sites.
Name_Dana Bahar
Title or official role (if any) Manager, Superfund Oversight Section
Ground Water Quality Bureau, New Mexico Environment Department
Telephone number(505) 827-2908
Information provided General Background Information
Name_Mary Ann Menetrey
Title or official role (if any) Manager, Mining Environmental Compliance Section
Ground Water Quality Bureau, New Mexico Environment Department
Telephone number(505) 827-2944
Information provided General Background Information

